

From: [Moore, Gary](#)
To: ["Brenda Basile"](#)
Subject: RE: Drainage Area with Existing Oily Sludge
Date: Friday, June 05, 2015 7:54:00 AM

Brenda:

They are combinations:

Office Area Gate: (b) (6)

Wayland Street Gate (Temp Fence): (b) (6)

Gary Moore

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

moore.gary@epa.gov

From: Brenda Basile [mailto:Brenda.Basile@pbwllc.com]

Sent: Friday, June 05, 2015 7:55 AM

To: Moore, Gary

Subject: RE: Drainage Area with Existing Oily Sludge

Gary:

Are the locks on the gates keyed or combination? If they are keyed, can I get the keys from Weston (once the access agreement is signed and the EPA activities are finished)? If they are combination, can I get the combinations?

Thanks

Brenda

BPB-eSig



+++++CONFIDENTIALITY NOTICE+++++

This e-mail and the information contained herein may be confidential and/or protected by the attorney-client, work product or other applicable privilege. This e-mail is intended to be reviewed only by the individual or organization named above. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination, or copying of any portion of this e-mail, and/or any attachments, is prohibited. If you have received this e-mail in error, please immediately notify the sender by return e-mail and delete this e-mail from your system. Thank You.

From: Moore, Gary [mailto:Moore.Gary@epa.gov]

Sent: Friday, June 5, 2015 7:52 AM

To: Brenda Basile

Cc: Terry Andrews; Tighe, C. Daniel

Subject: CES: Drainage Area with Existing Oily Sludge

Brenda:

As we discussed yesterday, my contractor noticed an oily area that continues to remain flooded that when he walked through it caused a sheen on the water. This location is the original storm water drainage pathway for the site. I am not sure that it has ever been completely dry and still retains water today. It should have been obvious that this area likely contained oil from the spill that took place from the tanker trailer due to vandalism back at the end of July 2014 but we failed to address it. According to my contractor, he was pulling out pump and hose and walked through the area and it bubbled up oil and caused a sheen.

Since we have demobed equipment and it does not cause a sheen until disturbed, EPA will not address this and will leave it for the PRP Group to address. I have attached a map to give you the general vicinity of the location.

Thanks

Gary Moore

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

moore.gary@epa.gov